

Sikorsky  
124 Quarry Road Trumbull, CT 06611 Mailstop K100  
Telephone +1 203•683•2124 Mobile +1 203•535•8526



March 25, 2020

CCS-ALL-AOL-20-0004

To: All S-76® and S-92® Operators  
All Service Centers  
All Field Service Representatives

Attention: Aviation Director  
Chief of Maintenance  
Chief Helicopter Pilot

Subject: COVID-19 Virus - Aircraft Interior Cleaning Product Specifications

Sikorsky has received requests for cleaning practices for the S-92 and S-76 helicopter interiors. We would like to share the specifications for recommended cleaning products with all operators.

Customers can elect to use one of the two following aerospace material specifications that cover cleaning and disinfecting aircraft interiors:

1) SAE AMS1453A (or later revision), 'Disinfectant Cleaner for Aircraft Interior, General Purpose Liquid',

and/or

2) SAE AMS1452B (or later revision), 'Disinfectant, Aircraft General Purpose'.

Materials qualified to either or both of these specifications will not cause any corrosion, embrittlement, staining/discoloration, paint damage, etc.

Sikorsky does not endorse a specific product. Operators should consult with their local health authorities regarding the specific level of disinfectant for the target application.

Please contact your Customer Support Manager or local Field Service Representative if you have any questions regarding this letter.

Sincerely,



Joseph Lopez  
S-76 Program Manager  
Commercial Systems and Services  
[Joe.Lopez@LMCO.com](mailto:Joe.Lopez@LMCO.com)



John J. Mongelli  
S-92 Program Manager  
Commercial Systems and Services  
[John.Mongelli@LMCO.com](mailto:John.Mongelli@LMCO.com)